

# Tips from the gasket expert

## Engine failure – is the cylinder head gasket to blame?

# Gas blow-by on the metal layer gasket

# Metaloflex<sup>®</sup>

## Failure due to pressure build-up in the cooling system

### Damage symptoms:

Clear linear impressions visible on the multi-layer metal-elastomer cylinder-head gasket. These impressions were made by the cylinder-head sealing surfaces and run in the direction of the combustion chamber.



### Cause:



The surface structure of the cylinder head was machined either too coarsely or not at all. This caused combustion gas blow-by into the cooling circuit and overheating (pressure build-up).

### Other possible causes:

- The air was not removed entirely from the cooling system so the coolant did not circulate.
- Cooling circuit was interrupted (water pump, thermostat, fan).
- High exhaust back pressure caused engine to overheat (e.g. defective catalytic converter).

### Measures:

Check the condition of the sealing surfaces very closely before installation and ensure that the cylinder head is. If necessary resurfacing by a specialist.



Para-meters	Metal/soft-material	Multi-layer metal	Metal-elastomer
$R_z$	15 - 20 $\mu\text{m}$	11 $\mu\text{m}$	11 - 20 $\mu\text{m}$
$R_{\text{max}}$	20 - 25 $\mu\text{m}$	15 $\mu\text{m}$	15 - 20 $\mu\text{m}$
$W_t$		8-10 $\mu\text{m}$	